



Wood Environment & Infrastructure Solutions, Inc  
 200 American Metro Blvd., Suite 113  
 Hamilton, NJ 08619  
 Phone: (609) 689-2829 Fax: (609) 689-2838

## LETTER OF TRANSMITTAL

<b>TO:</b> Allan Williams Highland Park Environmental Commission  <b>FROM:</b> John Poserina, Project Manager	<b>DATE:</b> 08/10/2018  <b>PROJECT NO.:</b> 3480180606 <b>PROJ. NAME:</b> Honeywell Highland Park <b>SUBJECT:</b> Construction Air Monitoring Data for week of 062518 to 062918 Former Midland Ross Facility, SRP PI#018773 Highland Park, New Jersey
---	--

WE TRANSMIT TO YOU:                       HEREWITH                       UNDER SEPARATE COVER

**SUBJECT:**

- DRAWINGS
- SPECIFICATIONS
- CALCULATIONS
- REPORT
- COST ESTIMATE
- AS NOTED

**ACTION:**

- FOR YOUR INFORMATION
- FOR YOUR COMMENT OR APPROVAL
- RETURNED FOR CORRECTION: RESUBMIT
- APPROVED AS NOTED
- AS REQUESTED

**SENT BY:**

- MAIL
- CERTIFIED MAIL
- EXPRESS **Federal Express**
- COURIER
- HAND DELIVERED
- FACSIMILE:

36 pages (including transmittal sheet)

COPIES	DATE	DESCRIPTION
1	06/29/18	Construction Air Monitoring Data

**REMARKS:**

The following data package includes the following from the week of 062518 to 062918

- Map displaying Air Monitoring Station locations
- Dust Monitoring Results
- Laboratory Air Sample Results

Note: Monitoring delayed on 06/28/18 due to rain.

**CC:** Maria Kaouris - Honeywell  
Jorge Berkowitz, Ph.D, LSRP - Langan  
Kay Licausi  
 \_\_\_\_\_  
 \_\_\_\_\_

**By:** John Poserina, P.E.


**Direct Phone:** (609) 631-2923

**CONFIDENTIALITY NOTICE:** This message is intended only for the use of the individual or entity to which it is addressed, and may contain information that is privileged, confidential, and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, or the employee or agent responsible for delivering the message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address via the U.S. Postal Service. Thank you.

If transmission is not received in good order, please call Project Coordinator at (610) 828-8100.


# **AIR MONITORING STATION LOCATIONS**

UNLESS OTHERWISE AGREED IN A WRITTEN CONTRACT BETWEEN WOOD AND ITS CLIENT, (I) THIS DOCUMENT CONTAINS INFORMATION, DATA AND DESIGN THAT IS CONFIDENTIAL AND MAY NOT BE COPIED OR DISCLOSED, AND (II) THIS DOCUMENT MAY ONLY BE USED BY THE CLIENT IN THE CONTEXT AND FOR THE EXPRESS PURPOSE FOR WHICH IT HAS BEEN DELIVERED. ANY OTHER USE OR RELIANCE ON THIS DOCUMENT BY ANY THIRD PARTY IS AT THAT PARTY'S SOLE RISK AND RESPONSIBILITY.



**LEGEND:**

- PROPERTY BOUNDARY (FORMER MIDLAND-ROSS FACILITY)
- PROPOSED EXCAVATION AREA (AOC MR-8)
- FORMER JANEWAY-CARPENTER BUILDING CONCRETE SLAB REMOVAL AREA
- AMS-1 PROPOSED AIR MONITORING STATION LOCATION



SOURCE MAP REFERENCE:  
DRAWING TITLED "TOPOGRAPHIC SURVEY, BLOCK 170, LOTS 5 & 6, BOROUGH OF HIGHLAND PARK, COUNTY OF MIDDLESEX, STATE OF NEW JERSEY" DATED 1/9/2017 BY MASER CONSULTING P.A., MOUNT ARLINGTON, NEW JERSEY, PROJECT NUMBER 16001990A

REV.	DATE	STATUS	PRPD BY	CHKD BY

WOOD PROJECT No. 3480170577  
DRAWING: 3480170577-5200-RA00-0000

PREPARED/DATE:  
VMW 09/29/17

CHECKED/DATE:  
US 09/29/17

**wood.**

**ENVIRONMENT & INFRASTRUCTURE SOLUTIONS**  
200 AMERICAN METRO BLVD, SUITE 113  
HAMILTON, NEW JERSEY 08619

**FIGURE 1**  
PROPOSED PERIMETER AIR MONITORING STATION LOCATION  
HONEYWELL - FORMER MIDLAND-ROSS SITE  
HIGHLAND PARK, NEW JERSEY

**QUICK REFERENCE ACTION RESPONSE  
TABLE FROM PERIMETER AIR  
MONITORING PLAN**

Quick Reference Action Response Plan  
Former Midland Ross Facility  
Highland Park, NJ



**Quick Reference Action Response Plan**

Acute Dust <sub>PM-10</sub> Action Level	Action/Procedure
≥ 109 ug/m <sup>3</sup> + Background (duration of <b>less</b> than 5 minutes)	<ul style="list-style-type: none"> <li>• The PAMPT will observe PM-10 concentrations at the location of the exceedance. Make notification to SHSO. The PAMT and SHSO will attempt to identify the source of the PM-10 emissions. The SHSO will make preparations to address the source.</li>   <li>• Continue to observe PM-10 emissions.</li> </ul>
≥ 109 ug/m <sup>3</sup> + Background (duration of <b>more</b> than 5 minutes)	<ul style="list-style-type: none"> <li>• Document the time and PM-10 level within the air monitoring log or field log book. Prepare to collect confirmatory sample.</li> <li>• Implement use of engineering control measures if PM is sustained above 109 ug/m<sup>3</sup> for more than 5 minutes.</li>   <li>• Continue to observe PM-10 emissions.</li> </ul>
≥ 109 ug/m <sup>3</sup> + Background (duration of <b>more</b> than 15 minutes)	<ul style="list-style-type: none"> <li>• Cease intrusive activities. Document the time and PM-10 level within the air monitoring log or field log book.</li> <li>• Collect confirmatory sample.</li>   <li>• Re-evaluate work procedures and amend as appropriate. Continue monitoring and engineering control measures.</li> <li>• When PM-10 concentration falls below the Action Level (15 minute TWA), work may resume.</li> </ul>
Visible dust	<ul style="list-style-type: none"> <li>• Implement dust suppression measures (discretion of the PAMT).</li> </ul>

## **CONSTRUCTION AIR MONITORING DATA**



**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 1 6/25/2018**

**Air Monitoring Results**



**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 2 6/25/2018**



**Air Monitoring Results**







**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 3 6/25/2018**

**Air Monitoring Results**





**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 4 6/25/2018**

**Air Monitoring Results**





**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 5 6/25/2018**

**Air Monitoring Results**





**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 1 6/26/2018**

**Air Monitoring Results**





**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 2 6/26/2018**

**Air Monitoring Results**





**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 3 6/26/2018**

**Air Monitoring Results**





**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 4 6/26/2018**

**Air Monitoring Results**



**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 5 6/26/2018**



**Air Monitoring Results**







**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 1 6/27/2018**

**Air Monitoring Results**





**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 2 6/27/2018**

**Air Monitoring Results**





**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 3 6/27/2018**

**Air Monitoring Results**





**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 4 6/27/2018**

**Air Monitoring Results**





**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 5 6/27/2018**

**Air Monitoring Results**





**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 1 6/28/2018**

**Air Monitoring Results**





**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 2 6/28/2018**

**Air Monitoring Results**



**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 3 6/28/2018**



**Air Monitoring Results**







**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 4 6/28/2018**

**Air Monitoring Results**





**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 5 6/28/2018**

**Air Monitoring Results**





**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 1 6/29/2018**

**Air Monitoring Results**





**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 2 6/29/2018**

**Air Monitoring Results**





**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 3 6/29/2018**

**Air Monitoring Results**





**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 4 6/29/2018**

**Air Monitoring Results**



**Former Midland-Ross Site  
Highland Park, New Jersey  
Dust Monitoring Results  
Air Monitor 5 6/29/2018**

**Air Monitoring Results**



## **LABORATORY AIR SAMPLE RESULTS**



Analyte	CAS Number	Criteria	200-44121 AMS- 5-062618 3:50PM	Units	Qualifier
<b>Metals</b>					
Lead	7439-92-1	0.00049	0.000065	mg/m3 Filter	U
Copper	7440-50-8	0.49	0.00032	mg/m3 Filter	U
<b>PAHs</b>					
Phenanthrene	85-01-8	310	<b>0.066</b>	ug/m3 PUF	
Anthracene	120-12-7	31	0.030	ug/m3 PUF	U
Fluoranthene	206-44-0	310	0.030	ug/m3 PUF	U
Naphthalene	91-20-3	14.6	<b>0.12</b>	ug/m3 PUF	
Acenaphthylene	208-96-8	310	0.030	ug/m3 PUF	U
Acenaphthene	83-32-9	310	0.030	ug/m3 PUF	U
Pyrene	129-00-0	310	0.030	ug/m3 PUF	U
Indeno[1,2,3-cd]pyrene	193-39-5	3.1	0.030	ug/m3 PUF	U
Benzo[a]pyrene	50-32-8	3.1	0.030	ug/m3 PUF	U
Benzo[g,h,i]perylene	191-24-2	31	0.030	ug/m3 PUF	U
Dibenz(a,h)anthracene	53-70-3	0.3	0.030	ug/m3 PUF	U
Chrysene	218-01-9	31	0.030	ug/m3 PUF	U
Benzo[a]anthracene	56-55-3	0.3	0.030	ug/m3 PUF	U
Benzo[k]fluoranthene	207-08-9	3.1	0.030	ug/m3 PUF	U
Benzo[b]fluoranthene	205-99-2	3.1	0.030	ug/m3 PUF	U
<b>VOCs</b>					
Chlorobenzene	108-90-7	4867	0.9	ug/m3	U
Ethylene Dibromide	106-93-4	3.9	2	ug/m3	U
Ethylbenzene	100-41-4	4867	0.9	ug/m3	U
o-Xylene	95-47-6	487	0.9	ug/m3	U
Styrene	100-42-5	4867	0.9	ug/m3	U
m-Xylene & p-Xylene	179601-23-1	487	2	ug/m3	U
Chlorodibromomethane	124-48-1	12.6	2	ug/m3	U

Analyte	CAS Number	Criteria	200-44121 AMS- 5-062618 3:50PM	Units	Qualifier
4-Methyl-2-pentanone (MIBK)	108-10-1	14600	2	ug/m3	U
Toluene	108-88-3	24333	2	ug/m3	
Dichlorobromomethane	75-27-4	9.2	1	ug/m3	U
cis-1,3-Dichloropropene	10061-01-5	97.3	0.9	ug/m3	U
Tetrachloroethene	127-18-4	195	1	ug/m3	U
trans-1,3-Dichloropropene	10061-02-6	-	0.9	ug/m3	U
1,1,2-Trichloroethane	79-00-5	21.3	1	ug/m3	U
1,2,4-Trichlorobenzene	120-82-1	9.7	4	ug/m3	U
1,2-Dichlorobenzene	95-50-1	973	1	ug/m3	U
Hexachlorobutadiene	87-68-3	15.5	2	ug/m3	U
Ethanol	64-17-5	-	10	ug/m3	
Naphthalene	91-20-3	14.6	3	ug/m3	U
1,4-Dichlorobenzene	106-46-7	3893	1	ug/m3	U
4-Ethyltoluene	622-96-8	-	1	ug/m3	U
1,3,5-Trimethylbenzene	108-67-8	-	1	ug/m3	U
Bromoform	75-25-2	310	2	ug/m3	U
1,1,2,2-Tetrachloroethane	79-34-5	5.9	1	ug/m3	U
1,3-Dichlorobenzene	541-73-1	-	1	ug/m3	U
2-Chlorotoluene	95-49-8	-	1	ug/m3	U
1,2,4-Trimethylbenzene	95-63-6	-	1	ug/m3	U
Carbon disulfide	75-15-0	3407	2	ug/m3	U
Isopropyl alcohol	67-63-0	-	12	ug/m3	U
Acetone	67-64-1	150867	12	ug/m3	U
1,1-Dichloroethene	75-35-4	2433	0.8	ug/m3	U
Methyl tert-butyl ether	1634-04-4	14600	0.7	ug/m3	U
2-Methyl-2-propanol	75-65-0	-	15	ug/m3	U
3-Chloro-1-propene	107-05-1	-	2	ug/m3	U

Analyte	CAS Number	Criteria	200-44121 AMS- 5-062618 3:50PM	Units	Qualifier
Methylene Chloride	75-09-2	2920	7	ug/m3	
Vinyl chloride	75-01-4	487	0.5	ug/m3	U
Butadiene	106-99-0	-	0.4	ug/m3	U
Chloromethane	74-87-3	438	1	ug/m3	
1,2-Dichloro-1,1,2,2-tetrafluoroethane	76-14-2	-	1	ug/m3	U
Dichlorodifluoromethane	75-71-8	487	2	ug/m3	U
1,1,2-Trichloro-1,2,2-trifluoroethane	76-13-1	146000	2	ug/m3	U
Trichlorofluoromethane	75-69-4	3407	1	ug/m3	
Vinyl bromide	593-60-2	-	0.9	ug/m3	U
Bromomethane	74-83-9	24.3	0.8	ug/m3	U
Chloroethane	75-00-3	48667	1	ug/m3	U
1,2-Dichloroethane	107-06-2	1947	0.8	ug/m3	U
n-Heptane	142-82-5	-	0.8	ug/m3	U
Benzene	71-43-2	14.6	0.9	ug/m3	
Isooctane	540-84-1	-	0.9	ug/m3	U
1,4-Dioxane	123-91-1	146	18	ug/m3	U
Methyl methacrylate	80-62-6	-	2	ug/m3	U
Trichloroethene	79-01-6	9.7	1	ug/m3	U
1,2-Dichloropropane	78-87-5	19.5	0.9	ug/m3	U
cis-1,2-Dichloroethene	156-59-2	-	0.8	ug/m3	U
2-Butanone (MEK)	78-93-3	24333	1	ug/m3	U
1,1-Dichloroethane	75-34-3	973	0.8	ug/m3	U
Hexane	110-54-3	-	1	ug/m3	
trans-1,2-Dichloroethene	156-60-5	-	0.8	ug/m3	U
Carbon tetrachloride	56-23-5	195	1	ug/m3	U
Cyclohexane	110-82-7	29200	0.7	ug/m3	U
1,1,1-Trichloroethane	71-55-6	4867	1	ug/m3	U

Analyte	CAS Number	Criteria	200-44121 AMS- 5-062618 3:50PM	Units	Qualifier
Chloroform	67-66-3	1460	1	ug/m3	U
Tetrahydrofuran	109-99-9	-	15	ug/m3	U

U -The compound was not detected at the indicated concentration.

J - Data indicates the presence of a compound that meets the identification criteria.

N - The presumptive evidence of a compound.\* - LCS or LCSD is outside acceptance limits.

\* - RPD of the LCS and LCSD exceeds the control limits.

The concentration given is an approximate value.

-- No criteria available.

**BOLD:** Analyte detected in sample.

**BOLD:** Exceedance above the NJDEP Division of Air Quality Toxicity Values for Inhalation Exposure, October 2017.